



Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
CARTER KNOWLE AVENUE	o/s 72	Dead	Dead	Crataegus monogyna	Plant in verge in same position o/s 72.	Crataegus laevigata 'Paul's Sc
CARTER KNOWLE AVENUE	o/s 46-48	Damaging	Damage to Surface	Prunus serrula	Plant in verge centrally between 46-48 (same as felled tree)	Malus 'Rudolph'
CARTER KNOWLE AVENUE	o/s 42-44	Damaging	Damage to Surface	Prunus serrula	Plant in verge centrally between 42-44 (same as felled tree)	Malus 'Rudolph'
CARTER KNOWLE AVENUE	o/s 22 (facing 11-13)	Damaging	Damage to Surface	Prunus serrula	Plant in verge centrally o/s 22 (same as felled tree)	Crataegus laevigata 'Paul's Sc